Volk Optical Inc
7893 Enterprise Drive
Mentor, 0H 44066 USA
Tel: 440-942-2616
Fax: 440-942-2257
Email: volk@volk.com

 (ϵ)

Volk Optical Contact Laser & Diagnostic Lenses (Direct Contact)

ENGLISH: INSTRUCTIONS FOR USE

INTENDED LISE

Contact Laser & Diagraphormalities.

SPECIFICATIONS

Product	Magnification	Laser Spot Magnification Factor	Available Contact Designs	Anti-Reflective Laser Coating
Centralis Direct®	0.90	1.11	Standard Fluid ANF+ (no fluid)	BBAR
Volk Fundus Laser	1.25	0.80	Standard Fluid	BBAR
Volk Fundus 20mm Laser	1.44	0.70	Standard Fluid	BBAR
Volk Capsulotomy	1.57	0.63	Standard Fluid	BBAR
Volk MagPlus Iridectomy	1.60	0.63	Standard Fluid	BBAR
Volk Iridectomy	1.70	0.58	Standard Fluid	BBAR
Volk Blumenthal Iridotomy	1.54	0.65	Standard Fluid	BBAR

INDICATIONS FOR USE

- To be used by a licensed physician in a method consistent with other direct image ophthalmic contact laser & diagnostic lens. Inspect the contacting surface(s) to make sure they are free from any damage (e.g. chips, scratches, etc.). Standard Fillul and NF Flange (NF) contact lenses require methylosibulose or other similar inferice solution be applied to the concave contact
- 3 ANF-contact lenses require a normal tear solution be applied to the concave contact surface.

 Volk's BBAR Anti-Reflective Laser Coating is optimized for diagnostic imaging, as well as visible and near-infrared wavelength laser procedures (e.g. argon & diode).
- 5
- 6
- (e.g. argon A codes). When calculating the spot size at the retina, the laser spot setting should be multiplied by the appropriate Laser Megnification Factor. Refer to the Specifications bable to find the appropriate Laser Megnification Factor for the lens you are using. When using MegNight indicatorily lens, the best results are obtained when working in reference to the silver machine mark along the outer housing which indicates the apex of the lens.

 When using Blumenhell indicatorily lens, the best results are obtained when working between the two reference marks within the anterior of the
- 8

MARNING:

DO NOT USE THE LENS WHEN THE CONTACTING SURFACE(S) SHOW(S) ANY SIGNS OF DAMAGE

DO NOT ATTEMPT TO USE THE LENS UNLESS AN ADEQUATE TYPE AND AMOUNT OF COUPLING FLUID IS PRESENT BETWEEN THE CORNEA AND THE CONTACTING LENS SURFACE.

REPROCESSING

MARNING:

NG: A THOROUGH, MANUAL CLEANING PROCESS IS RECOMMENDED

CORROSIVE CLEANING AGENTS (I.E. ACIDS, ALKALINES, ETC) ARE NOT RECOMMENDED. DETERGENT CLEANING AGENTS WITH NEUTRAL PH ARE RECOMMENDED.

PREPARATION AT THE POINT OF USE

- New or used, contaminated lenses must be cleaned.

 Body fluids should not be allowed to dry on the unit prior to cleaning. Remove excess body fluids.

 Universal precautions for handling contaminated materials should be coberved.

 Instruments should be cleaned as soon as possible after use to minimize the drying of contaminants to the surface.

 Instruments should be cleaned as soon as possible after use to minimize the drying of contaminants to the surface.

 Devices should always be handled in an appropriate method to ensure contamination is not introduced to a recently cleaned, disinfected, and/or starting device.

REPROCESSING LIMITATIONS:

Repeated cleaning, disinfection, and sterilization have minimal effect on Volk Indirect Contact Lenses when process the product's life cycle is normally determined by wear and damage due to use. PREPARATION REFORE CLEANING

on instructions are aided by not allowing contamination to dry on the lens surface. When possible place

The following cleaning, disinfection, and sterilization the lenses in water or cover them with a damp cloth.

CLEANING, DISINFECTION, STERILIZATION CLEANING:

ect the desired method of cleaning

Method A:	the retaining ring within the housing. Do not use detergents containing Emollients (moisturizers).				
Method B:	Clean the glass element with Volk Precision Optical Lens Cleaner (POLC) or a Volk LensPen®. Clean lens surface in a clockwise direction to help prevent loosening of the retaining ring within the housing. 6.4UTION: Do not use Volk's POLC, or the Volk LensPen® on surfaces that confact the eye.				
Method C:	Prepare fresh enzymatic cleaner (e.g. Erzol) solution – 2 ounces per gallon using were (~30 - 43°C) tap water. Soak each device in solution for 20 minutes. Alter soaking, brush knuried surface on device ring with a soft-tristle brush and uple lens portion with a soft cloth until all traces of cleaner and soil are removed. Clean lens surface in a clockwise direction. Pay special attention to all crevices and other hard-to-reach areas. NOTE: Do not brush lens portion to avoid scratching; use soft cloth. 4. Thoroughly rinse devices in a room temperature by awater bath (not under running water) until all visible cleaner has been removed. 5. Transfer the device(s) to a freshly prepared enzymatic solution (per step 1 above) and sonicate for 20 minutes. 6. After sonication, throroughly first device(s) in a room temperature by any text bath (not under running water) until all visible cleaner has been removed. 7. Inspect each device for remaining debris. If any is observed, repeat the cleaning procedure with freshly prepared cleaning solutions.				

CAUTION:

- Follow the **Method A** cleaning instructions.
 Select **one** of the solution types from the table belo

DISINFECTANT	CONCENTRATION	MIN SOAK TIME	MAX SOAK TIME
Glutaraldehyde	2% aqueous solution	25 minutes	N/A
Sodium hypochlorite (5000 ppm NaCIO)	9-parts water:1-part household bleach (5.25% NaCIO)	10 minutes	25 minutes
Cidex OPA	See Manufacturer's Instructions	12 minutes	N/A

- 4
- Position he lens on its side, and then immerse he device completely in the selected districtant souron for the minimum of 20°C. Insure to first ill emens, hard-to-reach resex, and eliminate of prodests.
 Rinse thoroughly in a room temperature water bath (minimum of 20°C). Rinse by immersing device completely for a minimum of one min
 Manually flush all mensor or other hard-to-reach areas with water. Agitate device under water, bring above water level, then re-immerse.
 rinse procedure two additional times using fresh water.
- (CAUTION:

- OR DESI

STERILIZATION

- ENSURE THE DEVICE IS COMPLETELY SUBMERGED IN THE DISINTECTANT SOLUTION FOR THE ENTIRITY OF THE RECOMMENDED OR DESIRED SOAK TIME. DO NOT ALLOW THE DEVICE TO BECOME UNSUBMERGED FROM THE DISINFECTANT SOLUTION. EXTENDED EXPOSURE AND/OR EXPOSURE TO HIGHER CONCENTRATIONS OF SODIUM HYPOCHLORITE WILL RESULT IN ACCELERATED DEGRADATION OF THE PRODUCT.
- Follow the Method C cleaning instructions.
 Ethylene oxide sterilization is the preferred method of sterilization. Sterilize using a 2 hour cycle with a recommended temp exceeding 150°F) and a concentration of 600 mg/L.

 Do not sterilize tenses within standard (black leatherette) lens cases as they are not meant for use in sterilization systems. od of sterilization. Sterilize using a 2 hour cycle with a recommended temperature of 130°F (not

CAUTION:

TO AVOID PRODUCT DAMAGE, NEVER AUTOCLAVE OR BOIL LENSES OR ADAPTERS

nstruments should be stored in an area that provides protection from loss of steril